### **Manhole Inspection Summary** Manhole # S05GG1022MH Printed On: 6/10/2009 Page 1 of 3 Inspection ✓ Is Incomplete Rating: Record Plat: 05GG1 Node: 022 Status: Not Found Insp Date: 12/22/08 1:25 PM Incomplete Comments Crew: ADS4 Cannot Access - Buried - Manhole Existing Confirmed by Inspector: ADS3 **CCTV** Firm: ADS Location Address: REAR OF 3918 FERNHILL RD Cross Street: GARRISON AVE **Manhole** Type: Location: Ground Conditions: Dry Weather: Dry Subject To Ponding: None Prev. Rehab Comments ATTEMPTED LOCATION AT REAR OF EMPTY LOT. DUE TO DEBRIS CONTAINING METAL OBJECTS, METAL DETECTOR GAVE INCONCLUSIVE RESULTS. PROBING OF GROUND IN SUSPECT LOCATIONS DID NOT FIND MANHOLE LID. Cover Diameter: Shape: (in.) Length: (in.) Dist A/B Grade: (in.) Type: Sanitary Condition: Cover Material: Cast Iron Properties: Bolted Vented **Frame** Offset: (in.) Condition: Sound Cracked Leaks **Chimney / Frame Adjustment** Exists Material: Parged Height: (in.) Condition: Sound Cracked Root Intrusion ☐ Loose Brick ☐ Deteriorated Infiltration: None ☐ Joint ☐ Cracks ☐ Mortar ☐ Roots ☐ Wall Corbel Material: Parged Type: Condition: Sound Cracked Root Intrusion ☐ Loose Brick ☐ Deteriorated Infiltration: None Joint Cracks Mortar Roots Wall Barrel Material: Parged Shape: Diameter: (in.) Length: (in.) Condition: Sound Cracked Root Intrusion Loose Brick Deteriorated Infiltration: None Joint Cracks Mortar Roots Wall **Bench** Exists Material: Parged Condition: Sound Cracked Root Intrusion ☐ Deteriorated ☐ Leaks Debris Channel Material: Parged Channel Exposure: Fully Open Junc Dist: 0 nearest .5 ft. Azimuth: Condition: Sound Cracked Root Intrusion ☐ Deteriorated ☐ Leaks Debris

**Steps** 

Surcharge

Count:

Missing:

Evidence Of Surcharge

Corroded

Depth:

(ft.) Active Surcharge Present

# **Manhole Inspection Summary**

## Manhole # S05GG1022MH

Printed On: 6/10/2009 Page 2 of 3

# **Manhole Inspection Summary**

## Manhole # S05GG1022MH

Printed On: 6/10/2009 Page 3 of 3